ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
DASARAHALLI

Ward No.
14

Ward Name
Bagalakunte

Street ID
W0701, W0586, W0697, W0538, W0518, W0683, W0687, W

Street Name
NA, 1st Main Rd, East Park Reje Lyt, 6th Crs, Muthkurappa Lyt, 1st Crs

Significant Landmark
Bagalagunte

Segment No.
14/C-W0701/S094645

Total Length (m)
358.30

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	51.97	77.503672	13.058240	77.504126	13.058090	2nd Sross	Swd
2	82.18	77.502015	13.056011	77.502205	13.055367	Water plant	Swd
3	46.95	77.501546	13.055757	77.501979	13.055746	Doddamaranna layout main roas	Deadend
4	50.85	77.501567	13.055447	77.502036	13.055443	10 Cross	16th Cross
5	26.65	77.501020	13.055203	77.500927	13.054980	2nd Cross	3rd Cross
6	22.00	77.500191	13.056095	77.500180	13.055896	2nd Cross	3rd Cross
7	77.70	77.499840	13.056147	77.500552	13.056067	4th Cross	Deadend

Work Details

History of Road / Lane / Circles

Name of the Work
Construction of CC Drain Marammadevi Temple Surrounding Via Phoenix School Surrounding and other Cross roadsin Bagalagunte ward no 14

Sanctioned Estimated Amount (Rs.)
7600000

Sanctioned Year
2021-22

Year
2021 - 2022

Type of Work
Others

Other Work Type
CC Drain

Tender
Tender

Work Details

Job No. / Work Code
014-20-000116

Work Order No.
EE/DD/W O/06

Work Order Date
30/04/2021

Period of Extention

Defect Liability Period From
30/04/2021

Defect Liability Period To
29/04/2022

Multiple road involved with the same Job No/ Work Code #
No

Contractor Details

Zone: DASARAHALLI **Ward No:** 14 **Ward Name:** Bagalakunte **Street ID:** W0701, W0586, W0697, W0538,

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Dasarahalli Division, Bangalore - 560 057.

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶ್ರೀ. ದಾಪರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ. ಪಾ.ಪಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

2016-17 to 2020-21 Onti Mane Progress

Scanned by CamScanner

Name of Contractor
Sri MN Ramaiah

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released
6221273.62

Phone No.
9449448850

E Mail ID

EE DAS
Ranganath BK
Venkatesh
Sri Venka

Field Inspection Details

Number of Trees	Any Other Information	Name
6	Drain CC	Sri Venkatesh
Date of Inspection	**Remarks**	
24/09/2021	Work complete	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	CE DAS	27/09/2021	24/10/2021	APPROVED

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0701, W0566, W0697, W0538,

EXECUTIVE ENGINEER
Bruhat Bangalore Mahanagara Palike
Division, Bangalore - 560 057

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಪಿ. ದಾಸರಹಳ್ಳಿ ಉಪ ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಜಿ.ಜಿ.ಎಂ.ಪಿ
ಬೆಂಗಳೂರು-560073

Scanned by CamScanner

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0701, W0586, W0697, W0538,

EXECUTIVE ENGINEER
Brihat Bangalore Mahanagara Palike
Dasarahalli Zone, Bangalore - 560 057.

Scanned by CamScanner